|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Kavitha : 9964702826
Bharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drilling of Borewell in Mallasandra colony, BHEL mini colony.

Address: PK's slum, Ravindra nagara slum and Surrounding area in ward no. 13 Shettyhalli Sub Division.

Location: Near Sri Lakkamma Temple **Topography** Magnetic Soil

Soil Type : Gravatic Soil **Rock Type:** hard rock



RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 **Water Level :** 2.5"

Depth Recommended : 890 - 1100 **Yield :** 490 - 760 - 880

Casing Pipe Required : 50 - 55 MS **Aquifers :** G.P.H - 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Know... and experience, However no guarantee of Water will be given

Samrudhi Ground Water Consultant
#4, 2nd M in Road, 3rd ... Layout,
B... Mob:

Smt. Kavitha Singh

Scanned with CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Kavitha : 9964702826
Bharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drilling of Borewell in Mallasandra colony, BHEL mini colony,

Address: PK's slum, Ravindra nagara slum and Surrounding area in ward no.13 Shettyhalli Sub Division.

Location: Shettyhalli Main Road **Topography** Magnetic Soil

Soil Type : Gravatic Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6½ **Water Level :** 9".

Depth Recommended : 850-1170 **Yield :** 460-720-870

Casing Pipe Required : 50-55 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

Smt. Kavitha Singh

Scanned with CamScanner

Kavitha : 9964702826
Sharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name: Boring of Borewell for Nallurumba colony, BHEL mini colony,

Address: Nr's Shri. Rajendra Nagar Slum and Surrounding area in

ward no's Shettyhalli Sub Division

Location: Govt. School opposite Nallurumba Topography: Magnetic Soil

Soil Type: Granular Soil Rock Type: hard rock.



RECOMMENDATIONS

Dia of Bore well Bit: 6 Water Level: 9"

Depth Recommended: 950 - 1070 Yield: 450 - 780 - 880.

Casing Pipe Required: 58 - 57 MS Aquifers: G.P.H. 2000

PVC Outer Casing if Required: — Point Location: ☑ ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note: The survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience. However no guarantee of Water will be given

Ground Water Consultant

Smt. Kavitha Singh

Scanned with CamScanner

|| Sri Gangamma Krupe ||

Kavitha : 9964702826
Bharath : 98459 93652

ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drilling of Borewell in Mallasandra colony, BHEL mini colony, Pk's slum, Ravindra nagara slum and Surrounding area in Ward no.13 Shettyhalli Sub Division.

Address:

Location: opposite Uchangi Temple Pk's slum **Topography** Magnetic Soil

Soil Type : Gravatic Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6½ **Water Level :** 9"

Depth Recommended : 850 - 1070 **Yield :** 440 - 720 - 870

Casing Pipe Required : 50 - 55 MS **Aquifers :** G.P.H. 3000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience. However no guarantee of Water will be given

For Samrudhi Ground Water Consultant

Smt. Kavitha Singh

Scanned with CamScanner

|| Sri Gangamma Krupe ||

ಸಮೃದ್ಧಿ

Kavitha : 9964702826
Bharath : 98459 93652

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drilling of Borewell in Nallasandra colony, BHEL mini colony, PK's slum, Ravindra nagara slum and Surrounding area in ward no.13 Shettyhalli Sub division.

Location: Near Shree Shakti Bhavana **Topography** Magnetic Soil

Soil Type : Gravatic Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6½ **Water Level :** 2"

Depth Recommended : 850 - 1100 **Yield :** 450 - 650 - 870

Casing Pipe Required : 51 - 56 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

For Samrudhi Ground Water Consultant

Smt. Kavitha Singh

Scanned with CamScanner

|| Sri Gangamma Krupe ||

Kavitha : 9964702826
Bharath : 98459 93652

ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drilling of Borewell in Mallasandra colony, BHEL mini colony,

Address: PK's Slum, Ravindra nagara slum and Surrounding area in ward no.13 Shettyhalli Sub Division.

Location: Near Kanika Parameshwari Temple ↑Ravindra Nagara. **Topography** Magnetic Soil

Soil Type : Gravatti Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6 **Water Level :** 9"

Depth Recommended : 850-1100 **Yield :** 460-720-820

Casing Pipe Required : 50-54 MS **Aquifers :** G.P.H 2000

PVC Outer Casing if Required: — **Point Location :** 1 ☐ ☐ ☐

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

For Samrudhi Ground Water Consultant

Smt. Kavitha Singh

Scanned with CamScanner

ಬೆಂಗಳೂರು ಜಿ.ಎಸ್.ಎಸ್.ಆರ್.ಎಸ್ GATR

|| Sri Gangamma Krupe ||

Kavitha : 9964702826
Bharath : 98459 93652

ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATION

Name : Drilling of Borewell in Mallasandra colony, BHEL mini colony,

Address: PK's Slum, Ravindra nagara slum and Surrounding area in ward no.13 shettyhalli Sub Division.

Location: 1st Cross Ravindra Nagara. **Topography** Magnetic Soil

Soil Type : Gravatti Soil **Rock Type:** hard rock.



RECOMMENDATIONS

Dia of Bore well Bit : 6½ **Water Level :** 9"

Depth Recommended : 820 - 1070 **Yield :** 460 - 680 - 860.

Casing Pipe Required : 51 - 57 MS **Aquifers :** G.P.H. 2000

PVC Outer Casing if Required: — **Point Location :** 1

Remarks:

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge, Exp and experience, However no guarantee of Water will be given

Smt. Kavitha Singh

Scanned with CamScanner